

PAPER • OPEN ACCESS

Prevention of crack in stretch flanging process using hot stamping technique

To cite this article: Y Mohd Syafiq *et al* 2017 *IOP Conf. Ser.: Mater. Sci. Eng.* **257** 012071

View the [article online](#) for updates and enhancements.

Related content

- [Improvement of formability of high strength steel sheets in shrink flanging](#)
Z Hamedon, Y Abe and K Mori
- [Experimental study on the warm forming and quenching behavior for hot stamping of high-strength aluminum alloys](#)
J Degner, A Horn and M Merklein
- [The comparison of two continuum damage mechanics-based material models for formability prediction of AA6082 under hot stamping conditions](#)
Z Shao, N Li and J Lin

Prevention of crack in stretch flanging process using hot stamping technique

Y Mohd Syafiq, Z Hamedon*, Wan Azila Aziz and Ahmad Razlan Yusoff

Faculty of Manufacturing Engineering, Universiti Malaysia Pahang,
26600 Pekan, Pahang Darul Makmur, Malaysia

*Corresponding author: zamzuri@ump.edu.my

Abstract. Demand for enhancing of passenger safety as well as weight reduction of automobiles has increased the use of high strength steel sheets. As a sheet metal is a lightweight having high strength is suitable for producing automotive parts such as white body panel. The stretch flanging of the high strength steel sheet is a problem due to high springback and easy to crack. This study uses three methods to stretch flange the sheets; using lubricants, shear-edge polishing and hot stamping. The effectiveness of these methods will be measured by comparing the flange length of each methods can achieved. For stretch flange with lubricant and polished sheared edge, the flange length failed to achieve the target 15 mm while hot stamping improved the formability of the sheet and preventing the occurrence of the springback and crack. Hot stamping not only improved formability of the sheet but also transformed the microstructure into martensite thus improve the hardness and the strength of the sheet after been quenched with the dies.

1. Introduction

Environmental sustainability in transportation especially passenger vehicle is important and crucial issue and the main dispute agenda are linked to have a better materials and efficient energy [1]. For passenger vehicles, the main contribution which can be consider is to reduce fuel consumption and exhaust emission levels is related to the weight reduction thus increased the application of high strength steel sheets. High strength steel sheet is one of the commonly used material that having high tensile strength about 490 MPa to 790 MPa. The highest grades are known to be used, 1180 MPa and 980 MPa class ultra-high strength steels for cold stamping was applied in structural parts. Table 1 shows the types of steel sheets with their respective tensile strength and strength-to-specific gravity ratio.

Table 1. Metals together with their tensile strength and strength-to-specific gravity ratio [2].

Sheet materials	Tensile strength (MPa)	Strength-to-specific gravity ratio (MPa)
Ultra-high strength steel sheet	980 - 1470	126 - 188
High strength steel	490 - 790	63 - 101
Mild steel SPCC	340	44

Besides, 980 MPa grade hot rolled ultra-high strength steel sheets is used in stamping of chassis although it is difficult to adopt high strength steels due to safety, durability and rigidity issues [3]. For



exposed panel, 590 MPa grade high strength steel sheets are applied although the exposed parts need a very fine surface quality. In automotive industry, specifically, a high strength steel sheet can produce a white body part to reduce the weight of body panels [4]. As the weight of the body panels decreases, the fuel consumption also is decrease. Takahashi mentioned an automotive industry has been trying to reduce the fuel consumption of vehicle with development of program; for example, are Partnership for a New Generation of Vehicles (PNGV) of United States; which are development of 80 miles per gallon car, and the development of 100 km per 3 litter cars in Europe [5]. However, the problems encounter as it's produced a large effect of springback and the crack formation towards the material during the stamping operation either bending or flanging process. These problems will affect the dimensional accuracy and appearance of the manufactured parts. Besides, this will contribute to assembly difficulties [6]. Hamedon et al. used stopper too prevent the fracture at the flip edge of the hemming [7]. Mori et al. discussed the method to improve the stretch flange ability by smoothing of sheared edge [8]. The in-situ deformation of the sheet during stretch flanging was observed using borescope was used by Hamedon et al. to understand actual phenomenon occurred [9]. The quality of the sheared edge influenced the limiting expansion ratio. By improving the limiting expansion ratio, the stretch flange ability is increased. Kim and Park discussed that the formability is affected by the parameters considerations during the stamping thus suggesting that improvement of the formability can be done by using ball tools with certain size is used with a small feed rate and a little friction. This is due to the plane-anisotropy; the formability is differed base on the direction of the tool movements [10]. Kusumi et al. stated that it is possible to predict fracture of steel sheet by studying the thickness reduction and mentioned that hot stamping permits the high strength steel sheets to be formed with good shape fix ability [11]. Maeno et al. improved the formability of titanium using resistance hot stamping [12]. This is the effect of the martensitic transformation during quenching after forming.

The objective of this study is to obtain the best method for stretch flanging of the high strength steel without fracture. In this research, the flange length is targeted to achieve 15 mm for each method that are going to be examined.

2. Experimental setup

The experimental setup is shown in the Figure 1 below. The blank size is 170 x 100 x 2 mm. The die set are as shown in the figure. High strength steel sheet is hold by the blank holder and the flange length are measured. The blank is sheared into the dimension first before sheared at the edge to produce V-shape edge for the stretch flanging process.




Figure 1. The experimental setup for stretch flanging and the flange length measurement.

Figure 2 show the stretch flanging operation. The corner edge will have a large tensile stress during the stretch flanging process.




Figure 2. Stretch flanging process with flat bottoming punch.

3. Preliminary experiment

Specimens are produced from the process of EDM wire cutting. The wire speed is set at 50 mm/min and the spindle feed at 5 rev/min. The finished product is shown in figure 3(a) with the dimension 100 x 10 x 2 mm. The cutting direction with consider the orientation is shown in figure 3(b). Tensile test is conducted for a specimen under a room temperature, heated at 700°C, 800°C and 900°C. Figure 3(c) shows the physical changes after the specimen is extended. The result from the tensile test are shown in Figure 4.



Figure 3(a). The finished specimen after wire cutting process.



Figure 3(b). The cutting direction with considering different orientation.




Figure 3(c). The specimen before and after tensile test




Figure 4. Stress strain graph for 0° orientation. The specimen is heated at 700°C.

From this test, the results show the mechanical properties obtained from the test for a different orientation heated under different temperature. Stress strain graph acquired shows the pattern of the graph before and after the materials undergo plastic deformation. By referring to the graph, the value of tensile stress at maximum load is 420 MPa whereas yield stress is about 342 MPa. The specimen starts to deform and fracture at 278 MPa.




Figure 5. Graph of tensile strength against temperature.

For the x-orientation, tensile strength decreases the temperature increases. Differ from y and z-orientation; they achieved a maximum tensile strength at 900°C. For z-orientation, it gives the highest value of tensile stress compare to the others (refer Figure 5). However, the higher the strength of the material, manufacturing will be more challenging and difficult. Based on this results, the process proceeds with x-orientation, the commonly used direction when perform a stamping with high temperature ranging 700°C to 800°C when heated. This is because the material was at the best condition so that the stamping process can easily conducted and fracture may be prevented.

Generally, good hardness means that the material is high resistant to scratching and wear. It is commonly used because they are quick and convenient for assessing material properties. Hardness Vickers test is applied during this research. The surface of the material was grind and polished to have flat and smooth surface. The mould is prepared for the specimen as shown in Figure 6. Then, diamond is indented along the surface. The hardness values appear on the PC screen after the indented area is

calculate. Based on the graph, the distribution of hardness values under different temperature do not shows consistency in plotted graph. The values range between 120HV to 180HV. The high strength steel sheets achieved the highest hardness when heated with 800°C.



Figure 6. After polished and mounted. The specimens are prepared for hardness test.




Figure 7. Graph of hardness versus temperature.

4. Results and discussion

Result obtained from the stamping process are shown in Figure 8. For the first attempt, the sheet is tested at room temperature. As can be seen, the fracture formed at the flanged area. This is due to the unheated material has a high tensile strength compared to heated material. Therefore, the material is hard to form and crack is highly occurring in this case.




Figure 8. Specimen after stamping operation. At room temperature, the high strength steel sheets fractured as shown in the circle.

The next test is with the same condition; the sheet does not undergo heating process but the sheet is flip to another side to identify whether there is a crack formation when stamping is performed. The result remains the same as the fracture still occurs on the material. It is due to the burr formation after cutting the material into V-shape.




Figure 9. Specimen after stamping operation. In reverse position, where the high strength steel sheets are flipped to other side; fracture occurs as shown in the circle.

Another steel sheets are applied with light oil which is coolant oil around the surface cutting area. However, the problem still occurs as there is no effect although the oil is applied to the surface. Oil usually acts as the cooling reagent and heat can be reduces during stamping operation.



Figure 10. Specimen after stamping operation with applying light oil (coolant oil) to the surface. Fracture occurs as shown in the circle.

The next high strength steel sheets are applying with heavy oil which is grease. But the crack still occurs around the flange part. It shows that there is no effect although the material is applied with oil.




Figure 11. Specimen after stamping operation with applying heavy oil (grease) to the surface. Fracture occurs as shown in the circle.

Another sheet is polished with sand papers to remove the burr. Burr is the main problems as more stress will be concentrated at the flange area. The effect of excessive stress to the material are the fracture may occur as shown in Figure 12.



Figure 12. Specimen after stamping operation. The surface was polished to remove the burr. Fractures still occur as shown in the circle.

The remaining high strength steel sheets are heated under different temperature which are 700°C, 725°C, 750°C and 800°C. heating process assist the mechanical structure of the sheets so that the fracture can be prevented. As shown in Figure 13, for all temperature used; there is no fracture form but only contribute to the thickness distribution along the edge.




Figure 13. Specimen that are heated. The flange part is good (no fracture)

Thickness distribution of the flanged part shows a slightly different for the different temperature. Figure 14 shows the distribution sheets thickness that has been measured. The measured point is 2 mm from the centre line of the flanged sheets and the distances from point to point are fixed to 2 mm.




Figure 14. Specimen that are heated are only showing different in thickness distribution at the numbered region.

From the graph; at point 1, thinning occurred where the thickness was reduced for all temperature tested. At point 2 also thinning are occurred except for the sheets that are heated with 800°C where the thickness remains at 2 mm. Point 3 and 4 are where thickening occurred and the highest value is 2.15 mm, for sheets that are heated at 800°C. Based on the figure, the lowest thickness distribution is for the sheets with heating temperature 800°C where the thinning at point 1 are by 0.2 mm and the thickening recorded is 0.15 mm. Thickness reduction will contribute to fracture of the sheets. Therefore, the smaller reduction is better for prevention of fracture in high strength steel sheet.




Figure 15. thickness distribution of high strength steel sheets.

5. Conclusions

It is found that among the factor that contributed to the fracture is the formation of burr and the crack at the edge of the sheet initiate the fracture thus polishing the sheet edge is one of the best solutions to this problem and it will be more successful if the material is polished before heated. Study also showed that applying oil does not contributed the prevention of fracture to the steel sheets. However,

through heating up the sheet before flanging had increase the formability of the high strength steel. Fracture or crack are prevented by hot stamping. The length of the flange is increased by using this method. Heating process helps to reduce the strength of the materials so that the forming process will easily performed. Lastly, the result obtained will be much better when a stamping is done.

References

- [1] Ingarao G, Di Lorenzo R and Micari F 2011 *J. Cleaner Production* **19** 337-47
- [2] Mori K, Maki S and Tanaka Y 2005 *CIRP Annals – Manufac.Tech.* **54** 209-12
- [3] Hasnulhadi J, Mori K and Abe Y 2014 *Procedia Eng* **81** 843-48
- [4] Hamedon Z, Abe Y and Mori K 2001 *Materials. Sci. and Eng.* **114** 01
- [5] Takahashi M, Uenishi A and Kuriyama Y 2000 *Nippon Steel Technical Report* 81.0
- [6] Gan W and Wagoner R H 2004 *Inter. J. Mech. sciences* **46** 1097-113
- [7] Hamedon Z, Mori K and Abe Y 2014 *Procedia Eng.* **81** 2074-79
- [8] Mori K, Abe Y and Suzui Y 2010 *J. Materials Processing Tech.* **210** 653-59
- [9] Hamedon Z, Mori K and Abe Y 2014 *J. Materials Processing Tech.* **214** 945-50
- [10] Kim Y H and Park J J 2002 *J. Materials Processing Tech.* **130–131** 42–6
- [11] Kusumi K, Nomura N and Maki J 2013 *Nippon Steel Technical Report* no. 103
- [12] Maeno T, Mori K and Hamedon Z 2012 *Steel Research Inter.* **SPL. ISSUE** 287-90