

REFERENCES

- Aggelis, D. G., Kordatos, E. Z., Soulioti, D. V., & Matikas, T. E. (2010). Combined use of thermography and ultrasound for the characterization of subsurface cracks in concrete. *Construction and Building Materials*, *24*(10), 1888–1897.
<https://doi.org/10.1016/j.conbuildmat.2010.04.014>
- Bissonnette, B., Vaysburd, A. M., & Fay, K. F. von. (2012). Best Practices for Preparing Concrete Surfaces Prior to Repairs and Overlays, (May), 92.
- Brief, A. (2008). Nondestructive Concrete Testing.
- Cotič, P., Kolarič, D., Bosiljkov, V. B., Bosiljkov, V., & Jagličić, Z. (2015). Determination of the applicability and limits of void and delamination detection in concrete structures using infrared thermography. *NDT & E International*, *74*, 87–93. <https://doi.org/10.1016/j.ndteint.2015.05.003>
- CPWD. (2002). Handbook on Repair and Rehabilitation of RCC Buildings.
- FLIR Systems Inc. (2014). FLIR ONE Fast Facts Tech Specs.
- Guo, S., Dai, Q., Sun, X., & Sun, Y. (2016). Ultrasonic scattering measurement of air void size distribution in hardened concrete samples. *Construction and Building Materials*, *113*, 415–422. <https://doi.org/10.1016/j.conbuildmat.2016.03.051>
- Lourenço, T., Matias, L., & Faria, P. (2017). Anomalies detection in adhesive wall tiling systems by infrared thermography, *148*, 419–428.
<https://doi.org/10.1016/j.conbuildmat.2017.05.052>
- Maierhofer, C., Brink, A., Röllig, M., & Wiggerhauser, H. (2003). Detection of shallow voids in concrete structures with impulse thermography and radar. *NDT and E International*, *36*(4), 257–263. [https://doi.org/10.1016/S0963-8695\(02\)00063-4](https://doi.org/10.1016/S0963-8695(02)00063-4)

- Mohammed, T. U., & Mahmood, A. H. (2016). Effects of maximum aggregate size on UPV of brick aggregate concrete. *Ultrasonics*, *69*, 129–136.
<https://doi.org/10.1016/j.ultras.2016.04.006>
- Nmai, C. K. (1999). ACI Education Bulletin E1-99 Developed by Committee E-701 ., *Methods*, 1–26.
- Popovics, J. S. (2005). Ultrasonic Testing of Concrete Structures. *Materials Evaluation*, 50–55. Retrieved from
<http://www.csa.com/partners/viewrecord.php?requester=gs&collection=TRD&recid=200312B2C0508EC>
- Portland Cement Association. (2002). Types and Causes of Concrete Deterioration. *PCA R&D Special N. 2617*, 1–16.
- Rackham, J. W., Couchman, G. H., Hicks, S. J., Engineering, T., Group, D., Institutions, O. F., ... Required, A. (2015). United States Patent [191. *Engineering Structures*, *102*(1), 2121–2136. <https://doi.org/10.1017/CBO9781107415324.004>
- Scott, M. (1997). Determining the Air Void Parameters of Concrete Using Digital Image Analysis of Polarized Light Micrographs Keywords :
- Soudki, K. A. (2001). Concrete Problems and Repair Techniques, 1–20. Retrieved from <http://www.epicuro.co.uk/uploads/cr1-9.pdf>
- Star, T., & Committee, T. (2011). STAR 193 - RLS Bonded Cement - Based Material Overlays for the Repair , the Lining or the Strengthening of Slabs or Pavements
 This publication has been published by Springer in This STAR report is available at the following address : Please note that the.
- Sutan, M., Faculty, M., & Samarahan, K. (2015). a Comparison Between Direct and Indirect Method of Ultrasonic Pulse Velocity in, *8*(5), 1–8.

- Turgut, P., & Kucuk, O. F. (2006). Comparative relationships of direct, indirect, and semi-direct ultrasonic pulse velocity measurements in concrete. *Russian Journal of Nondestructive Testing*, 42(11), 745–751.
<https://doi.org/10.1134/S1061830906110064>
- Yaman, I., Inci, G., Yesiller, N., & Aktan, H. M. (2001). Ultrasonic pulse velocity in concrete using direct and indirect transmission. *ACI Materials Journal*, 98(6), 450–457. Retrieved from http://digitalcommons.calpoly.edu/cenv_fac/195/