## THE DETECTION OF CONCRETE DEFECTS USING INFRARED THERMOGRAPHY

ABDULRAHMAN ARIF SAMEH

## B. ENG (HONS.) CIVIL ENGINEERING UNIVERSITI MALAYSIA PAHANG



## SUPERVISOR'S DECLARATION

I hereby declare that I have checked this thesis and in my opinion, this thesis is adequate in terms of scope and quality for the award of the Bachelor Degree of Civil Engineering.

(Supervisor's Signature) Full Name : Dr. Fadzil Bin Mat Yahaya Position : Lecturer Date : 8<sup>th</sup> January 2018



### **STUDENT'S DECLARATION**

I hereby declare that the work in this thesis is based on my original work except for quotations and citations which have been duly acknowledged. I also declare that it has not been previously or concurrently submitted for any other degree at Universiti Malaysia Pahang or any other institutions.

(Student's Signature)

Full Name : ABDULRAHMAN ARIF SAMEH

ID Number : AA13302

Date : 8<sup>th</sup> January 2018

# THE DETECTION OF CONCRETE DEFECTS USING INFRARED THERMOGRAPHY

## ABDULRAHMAN ARIF SAMEH

Thesis submitted in fulfillment of the requirements for the award of the Bachelor Degree in Civil Engineering

Faculty of Civil Engineering and Earth Resources

UNIVERSITI MALAYSIA PAHANG

JUNE 2017

#### ACKNOWLEDGEMENTS

First of all I am grateful to Allah who gives me sound mind & sound health to accomplish my final year project.

My sincere gratitude to my research supervisor Dr. Fadzil Bin Mat Yahaya, without his assistance and dedicated involvement in every step throughout the process, this thesis would have never been accomplished. I would like to thank you very much for your support and understanding over this past year.

Also thank to University Malaysia Pahang and all staff that help me in many way and their excellent co-operation especially during preparation and testing sample at laboratory, with their helps and guidance I have accomplished the Practical works according to the time.

Many thanks to my family for their support, encouragement and inspiration through these past years

## TABLE OF CONTENT

DEC	LARATION	
TITI	LE PAGE	
ACK	NOWLEDGEMENTS	ii
ABS	ГRАК	iii
ABS	ГКАСТ	iii
TAB	LE OF CONTENT	v
LIST	OF TABLES	ix
TAB	LE OF FIGURES	xi
СНА	PTER 1 INTRODUCTION	1
1.1	BACKGROUND	1
1.2	PROBLEM STATEMENT	3
1.3	OBJECTIVE OF RESEARCH	3
1.4	SCOPE OF WORK	3
1.5	EXPECTED OUTCOMES	4
1.6	SIGNIFICANT OF STUDY	5
СНА	PTER 2 LITERATURE REVIEW	6
2.1	HONEYCOMB IN CONCRETE	6
2.2	CRACKS IN CONCRETE	7

	2.2.1	CRACKING DUE DRYING SHRINKAGE	8
	2.2.2	CRACKING DUE THERMAL MOVEMENTS	8
	2.2.3	DETECTION OF CRACK IN CONCRETE	9
2.3	NON	DESTRUCTIVE TEST	10
	2.3.1	REBOUND HAMMER TEST	11
	2.3.2	ULTRASONIC PULSE VELOCITY	12
	2.3.3	INFRARED THERMOGRAPHY	13
		2.3.3.1 ACTIVE AND PASSIVE THERMOGRAPHY	14
		2.3.3.2 THEORETICAL CONSIDERATION	15
		2.3.3.3 ADVANTAGES OF THERMOGRAPHY	17
CHA	PTER 3	RESEARCH METHODOLOGY	19
3.1	INTRO	ODUCTION	19
3.2	EXPE	RIMENTAL PROCEDURE	20
3.3	MATE	ERIALS PREPARATION	21
	3.3.1	CONCRETE MANUFACTURING	21
	3.3.2	CEMENT	22
	3.3.3	WATER IN CONCRETE	23
	3.3.4	REINFORCEMENTS BARS	23
	3.3.5	AGGREGATE	24
3.4	RESE	ARCH METHODOLOGY	25

vi

	3.4.1	INFRARED THERMOGRAPHY CAMERA	25
3.5	EXPE	RIMENTAL DESIGN	27
3.6	ANAL	YSIS OF DATA	28
	3.6.1	IRT CALCULATION SYSTEM	28
CHA	PTER 4	RESULT AND DISSCUSION	29
4.1	INTRO	DDUCTION	29
4.2	INFRA	ARED THERMOGRAPHY IMAGE	30
	4.2.1	INFRARED THERMOGRAPHY IMAGE FOR CUBES	30
	4.2.2	IRT IMAGE FOR BEAMS	34
4.3	SOFT	WARE ANALYSIS	39
4.4	RESU	LT AND DISCUSSION FOR CUBES SAMPLES	40
	4.4.1	VALUE FROM CUBES' IRT IMAGE	40
	4.4.2	DISCUSSION FOR CUBE RESULTS	44
4.5	RESU	LT AND DISCUSSION FOR BEAMS SAMPLES	46
	4.5.1	VALUE FROM BEAMS' IRT IMAGE	46
	4.5.2	DISCUSSION FOR CUBE RESULTS	56
4.6	IRT IN	AGE FOR EXISTED STRUCTURE	59
CHA	PTER 5	CONCLUSION AND RECOMMENDATION	60
5.1	CONC	CLUSION	60
5.2	RECO	MMENDATION	61

vii

## REFRENCES

### LIST OF TABLES

Table 2.1: The electromagnetic spectrum	16
Table 3.1: Percentage of sand in each sample	27
<b>Table 4.1:</b> IRT Image when time is zero (sample 1)	30
Table 4.2: IRT Image after one hour (sample 2)	31
Table 4.3: IRT Image after two hours (sample 3)	32
<b>Table 4.4:</b> IRT Image after three hour (sample 4)	33
Table 4.5: IRT Image before and after flexural test (sample 1)	34
Table 4.6: IRT Image before and after flexural test (sample 2)	35
Table 4.7: IRT Image before and after flexural test (sample 3)	36
<b>Table 4.8:</b> IRT Image before and after flexural test (sample 4)	37
<b>Table 4.9</b> : IRT Image before and after flexural test (sample 5)	38
Table 4.10: Result from IRT image sample 1	40
Table 4.11: Analysed IRT image sample1	41
Table 4.12: Result from IRT image sample 2	41
Table 4.13: Analysed IRT image sample 2	42
Table 4.14: Result from IRT image sample 3	42
Table 4.15: Analysed IRT image sample 3	43
Table 4.16: Result from IRT image sample 4	43
Table 4.17: Analysed IRT image sample 4	44
Table 4.18: Result from IRT image (sample 1)	46
Table 4.19: IRT Image before and after flexural test (sample 1)	47
Table 4.20: Result from IRT image (sample 2)	48

Table 4.21: IRT Image before and after flexural test (sample 2)	49
Table 4.22: Result from IRT image (sample 3)	50
Table 4.23: IRT Image before and after flexural test (sample 3)	51
Table 4.24: Result from IRT image (sample 4)	52
Table 4.25: IRT Image before and after flexural test (sample 4)	53
Table 4.26: Result from IRT image (sample 5)	54
Table 4.27: IRT Image before and after flexural test (sample 5)	55

## **TABLE OF FIGURES**

Figure 1.1: Procedure of work	4
Figure 2.1: Typical appearance of drying shrinkage cracking	8
Figure 2.2: Thermal cracks in slabs	9
Figure 3.2: Experimental procedure	20
Figure 3.3: Constituents of concrete mixture	22
Figure 3.3: IRT camera fixed on tripod	28
Figure 4.1: IMAGEJ colour threshold	39
Figure 4.2: HUE detection for cube	39
Figure 4.3: HUE detection for beam	40
Figure 4.4: Percentage of sand vs area of red colour for each sample	45
Figure 4.5: Red area, % of sand and time after oven relationship	45
Figure 4.6: Sample 1 heated by oven	56
Figure 4.7: Sample 2 heated by oven	56
Figure 4.8: Sample 3 heated by sun	57
Figure 4.9: Sample 4 heated by sun	57
Figure 4.10: Sample 5 heated by sun	58
Figure 4.11: IRT for existed structure	59
Figure 4.12: Normal Image for existed structure	59

## LIST OF ABBREVIATION

IRT	Infrared Thermography
-----	-----------------------

- NDT Non-destructive test
- UPV Ultrasonic pulse velocity
- RC Reinforced concrete
- PT Pulsed thermography
- HSB Hue, Saturation and Brightness